

Printer UI Keyboard Shortcuts

V02.01
29 MAY 2024

Overview

This document provides a printable handout of keyboard shortcuts in the Printer UI.

This document includes the following sections:

1. Keyboard Shortcuts
2. Reference Location in Software

1. Keyboard Shortcuts

Shortcuts are current as of software release **v1.43**.

General Shortcuts	
Orient tool	Shift + O
Supports tool	Shift + S
Layout tool	Shift + L
Print controls	Shift + P
Project analysis	Shift + A
Toggle bounding boxes	Shift + B
Overhang detection	V
Measure	M
Toggle support opacity	U
Toggle part opacity	P
Toggle clip plane	C
Toggle platform	B
Change slider by 1	< or >
Change slider by 10	Shift + < or >
Toggle visibility for selected parts	H
Toggle visibility for all parts	Shift + H
Undo	Ctrl + Z
Redo	Ctrl + Shift + Z

Camera Control Shortcuts	
Rotate Camera 45°	Shift + S
Rotate Camera 90°	Shift + L
Zoom	Shift + P
Pan	Shift + A
Part Control Shortcuts *Active in Layout Mode	
Add parts to selection	Shift + Click drag
Remove parts from selection	Alt + Click drag
Duplicate selected parts	Shift + D
Delete selected part or supports	Backspace or del
*Move selected part ↑, ←, ↓, →	W, A, S, D
Hide label text	L
Show label text	S
Support Edit Shortcuts *Active in Manual Support Mode	
*Generate supports	Enter
*Deselect active polyline	Esc
*Edit point on a polyline	E + Click
*Snap to edge	Hold shift
*Specify second point of bar support	Hold CTRL

2. Reference Location in Software

